

Survey # WA-II-987 Approximate date ca. 1925-30
Street Address 76 North Main Street
Town, State Keedysville, Maryland
private X, public

Description

Typical of the 1925-30 period is this aluminum sided frame bungalow, said to be a Sears catalogue house. It is a one-and-a-half story structure with a deep porch beneath an overhang, and shed-roofed dormers front and rear. The porch columns are stuccoed and may indicate the original finish of this house. A small frame garage with bi-fold doors is located behind the house.

There are several bungalows in Keedysville, located at the edges of town. They may have been retirement homes for local farmers.


MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

- I. Geographic Organization: Western Maryland
- II. Chronological/Developmental Period(s):
Industrial/Urban Dominance
- III. Prehistoric/Historic Period Theme(s):
Architecture, Landscape Architecture, Community Planning
- IV. Resource Type
Category: Building
Historic Environment: Village
Historic Function(s) and Use(s):
Single Dwelling
Known Design Source: Unknown

Photo Reference: Photo # 6


Form Prepared By: Paula S. Reed, PhD, Architectural Historian
Preservation Associates, Inc.
19942 Lehmans Mill Road
Hagerstown, MD 21742

Date: 11/93



Keedysville Quadrangle

WA-II-987





WA-II-981, 986, 101

76, 74, 72, 10 N Main St. Kershysville, VA.

SE view, 10+ W elevation.

10/03

photo by H. Keen, Preservation Assoc Inc.

#6

1